

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**





FIG. 1

*FIG. 2*




FIG. 3




FIG. 4

8" Sensor Pipe Wall Thickness Sensitivity
Wavelength and 1st order Differencing




FIG. 5




FIG. 6




FIG. 7


Dimensional $k-\omega$ plot

FIG. 8(a)




FIG. 8(b)



Non-Dimensional $k-\omega$ plot

FIG. 8(c)

FIG. 8

Family of Calibration Curves



Sch 10	Sch 10		Sch 40		Sch 10		Sch 40		Sch 10		Sch 40	
	ID	delX/id	ID	delX/id	C ₂	C ₁	C ₂	C ₁	C ₂	C ₁	C ₂	C ₀
4.2900	55.94%	4.1030	58.49%	0.50	0.50	11.00	12.00	0.0150	0.0280			
6.4000	37.50%	6.1040	39.32%	0.50	0.46	8.00	6.50	-0.0060	0.0040			
8.3300	28.81%	8.0700	29.74%	0.50	0.36	5.80	2.80	-0.0100	-0.0100			
10.4450	22.98%	10.1110	23.74%	0.50	0.20	4.00	0.40	-0.0257	-0.0330			

FIG. 9